

POS	Qty.	Description	Material	(raw) Dimension	Remarks
R1	1	Bottom	light Ply	(3 x 155 x 35)	
R2	1	Nose Former	light Ply	3 x 31 x 22	
R3	1	Main Former	light Ply	3 x 35 x 32	glue R4 before assembly
R4	2	Reinforcement	birch Ply	0.8 x 32 x 10	
R5	1	Tow Hook Reinforcem.	Light Ply	3 x 4 x 55	
R6.1	1	Finger Rest	light Ply	3 x 22 x 25	for solid balsa Boom
R6.2	1	Finger Rest	light Ply	3 x 22 x 25	for carbon tube Boom
R7	1	Nose Reinforcement	light Ply	(3 x 15 x 30)	
R8	2	Nose Block	Balsa	(10 x 15 x 30)	
R9	2	Side	birch Ply	(0.8 x 195 x 40)	
R10	4	Side Reinforcement	light Ply	(3 x 4 x 10)	
R11	1	front Canopy Rest	birch Ply	(0.8 x 20 x 30)	
R12	1	rear Canopy Rest	birch Ply	(0.8 x 15 x 35)	
R13	1	front Canopy Tongue	birch Ply	(0.8 x 10 x 20)	
R14	1	rear Canopy Tongue	birch Ply	(0.8 x 10 x 35)	
R15	1	Canopy	birch Ply	(0.8 x 55 x 35)	
R16	1	Eye Screw	Metal	3 inner Diam. x 15	
R17	1	Tow Hook	Metal	2 x 10 x 15	
R18	1	Servo Tray	light Ply	(3 x 32 x 35)	adjust to your Servos
R19	2	Servo Mounting	light Ply	3 x 8 x 8	glue together
R20	1	Wood Srew	Metal	2 x 10	
R21	1	Boom Rest	light Ply	(3 x 25 x 3)	
R22	1	Plug	Plastic	3 x 20	
R23	1	Wood Srew	Metal	3 x 30	
R24	1	Plug Rest	Balsa	10.x.15 x 25	carbon boom only
R25.1	1	Boom	Balsa	15 x 20 x 430	
R25.2	1	Boom	Carbon tube	6 OD x 420	

Parts List Stabilizer

POS	Qty.	Description	Material	(raw) Dimension	Remarks
L1	1	Elevator	balsa	(2 x 70 x 180)	
L2	2	Reinforcement	balsa	(2 x 10 x 55)	
L3	1	V-Tail	balsa	(2 x 70 x 240)	
L4	1	Rudder	balsa	(2 x 70 x 110)	
L5	2	Horn	birch Ply	(1 x 15 x 17)	
L6	1	Hinge	tape	(15 x 600)	
L7	2	Pushrod	plastic	1.5OD x 500	
L8	2	Pushrod	wire	0.5OD x 500	

Parts List Wing KIS only

POS	Qty.	Description	Material	(raw) Dimension	Remarks
F1	1	main Wing	balsa	(8 x 75 x 780)	preshaped stock material
F2	1	leading Edge	spruce	(4 x 3 x 780)	preshaped stoch material
F3	1	trailing Edge	balsa	(2 x 30 x 780)	
F4	2	Winglet	balsa	(2 x 20 x 120)	

Parts List Wing BOBO only:

POS	Qty.	Description	Material	(raw) Dimension	Remarks
F9	1	trailing Edge	balsa	(3 x 15 x 780)	
F10	1	main Spar	balsa	(4 x 11 x 800)	
F11	1	leading Edge	balsa	(3 x 5 x 800)	
F12	1	leading Edge	spruce	(3 x 3 x 800)	
F13	2	Joiners	balsa	(6 x 11 x 10000)	
F14	2	Gussets	balsa	(3 x 10 x 10)	
F15	3	Ribs	balsa	(2 x 11 x 1000)	
F16	1	turbulator Spar	balsa	(3 x 3 x 800)	
F17	1	Dowel Rest	light Ply	(3 x 25 x 35)	
F18	1	Wing Mounting	balsa	(11 x 25 x 12)	

Parts List Wing KIS and BOBO

POS	Qty.	Description	Material	(raw) Dimension	Remarks
F5	1	Dowel	hard wood	3OD x 30	
F6	1	front Wing Rest	birch Ply	(0.8 x 35 x 25)	
F7	1	rear Wing Rest	birch Ply	(0.8 x 34 x 20)	
F8	1	Wing Mounting	birch Ply	1.5 x 15 x 15	

